Disassembly and Recycling Instructions

955°

Tori 3560, 3580 Tools Required:









Safety Glasses Wre

Metric Allen Wrenches

Hammer

Wrenchs/Ratchet



- 2. Face the chair down and Hammer the control while pulling on the base to saparate.
- 3. Separate the Cylinder from the base then recycle.
- 4. Face the Chair down and use the allen wrench to remove and unscrew the arms. Recycle Arms
- 5. Use a wrench to remove the control and then recycle.
- 6. Recycle the Seat and Back.

